


X-Carve – Using the Z-Probe



 Step 6: Touch the plate to the bit Touch the round brass touch plate to the end of the bit and hold it there for a second or two Easel will detect contact and advance to the next item on the screen without your needing to click on anything. If Easel does not detect contact, be sure your leads and clip are properly attached and try again. 	
 Step 7: Position the touch plate Set the round brass touch plate on the clamped material under the bit, so that when the bit lowers it will touch the plate. Click "Touch plate is in place" on the Easel screen. 	
 Step 8: Start probing Click "Start probing" on the Easel screen. The bit will slowly lower until it touches the brass plate. Watch to be sure the clip is not going to bump into the dust shoe rails and that the brass touch plate is indeed directly under the bit. 	
 Step 9: Put the Z-Probe away When the probing is finished, remove the clip, unplug the leads, and put the Z-Probe away. 	